



KR DRONEWORKS ADVISORY CIRCULAR

KRDW-AC 001, 5 May 2026

Reference: KRDW-RPAS / Mini 5 Pro V3.0, dated 21 April 26

INTRODUCTION

Recent DJI firmware updates have affected the controller app functionality, necessitating an amendment to the reference checklist. The safety tab setting for RTH and other safety settings can not be adjusted without both the controller and RPA powered on.

AMENDMENTS

1. Swap page 18 with page 19 such that the “Aircraft” page is now number 18 and the “Controller and Display” page is now page number 19.
2. New page 19 “Controller and Display” line 6 : “Power On” should now read “Power ON: Cont/RPA”. Line 12 : “Power Off” should now read “Power Off: RPA/Cont”

NOTE: The Caution remains in affect: Unfolding the rear arms with battery installed will power up the aircraft immediately unless disarmed.